p0115[3]


ZSW monitoring functions 2
r2198
Bit No.
Status word monitoring 2
0 Reserved
1 Reserved
2 Reserved
3 Reserved
From speed signals [8010.8]
4 1 = |n_set| < p2161
r2198.4
From speed signals [8010.8]
5 1 = n_set > 0
r2198.5
From torque signals, motor locked/stalled [8012.8]
6 1 = Motor blocked
r2198.6
7 Reserved
8 Reserved
9 Reserved
From torque signals, motor locked/stalled [8012.3]
10 1 = Torque setpoint < torque threshold value 1 (p2174)
r2198.10
From load monitoring [8013.8]
11 1 = Load monitoring signals an alarm
r2198.11
From load monitoring [8013.8]
12 1 = Load monitoring signals a fault
r2198.12
13 Reserved
14 Reserved
15 Reserved